

state of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Supervisor

March 15, 2006

Mine Name: Red Warrior Operator Name: L & M General Engineering & Construction, Inc. Inspector(s): Doug Jensen Other Participants: None Mine Status: Inactive	Inspection Time: 2:30	Date: Februa PM	
Elements of Inspection 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality	Evaluated	Comment	Enforcement
Purpose of Inspection: Inspected the site while in the area. Inspection Summary: The site had not changed since I visited and GPS were no changes, no photos or GPS data was collected. Conclusions and Recommendations: I will continue to monitor the site when I am in the		June 21, 2005	Because there
dj:pb cc: L&M Engineering & construction, Inc. John Blake ML 44686	<u> </u>	ate: <u>3/1</u>	5/06

